


Tamping unit overhaul under column B8:

(Option: second general overhaul already after three years)

2017 or 0 - 10,000 ⚡	2018 or after a maximum of 250,000 ⚡	2019 or a maximum of 500,000 ⚡	2020 or 0 - 10,000 ⚡	2021 or a maximum of 250,000 ⚡	2022 or a maximum of 500,000 ⚡	2023 or a maximum of 750,000 ⚡	2024 or a maximum of 1,000,000 ⚡	2025 or a maximum of 1,250,000 ⚡
I & II + Service booklet	IIIa Repair	IIIb Recommendation for repair	I & II + tamping tines	IIIa Repair	IIIb Recommendation for repair	IIIc Recommendation for repair	IIId Recommendation for repair	IIIe Recommendation for repair



Legend:

- BLUE** ... to be carried out by Plasser & Theurer
- RED** ... to be carried out by the machine operator (obligatory)
- ORANGE** ... to be carried out by the machine operator (optional)
- ⚡** ... Tamping cycle